## Division of Oil, Gas, & Mining

Mining Report 03/17/93 MINE ID: M0150030 MINE NAME: SINBAD MINE OPERATOR: WILSON, W.L. CONTACT: MR. W.L. WILSON ADDRESS: P.O. BOX 2183 GRAND JUNCTION CO 81502 PHONE: (303)243-7806 Surface Owner: BLM BLM #: Mineral Owner: BLM Lease #: Qtr-Qtr-Qtr1 Qtr1 Qtr1 Qtr-Qtr-Qtr2 Qtr-Qtr2 Qtr2 Sec Town Range SW 35 22.0S 10.0E Permit Status: APP Mine Type [(S)urface, (U)nderground]: U Mine Status (PRO, ACT, SUS, RET): SUS Acreage: Minerals Mined TENTATIVE APPROVAL FINAL APPROVAL LAST INSPECTED DATE RECEIVED DATE DATE 12/24/79 02/28/80 04/07/80 04/05/88 BOND TYPE: SURETY BOND BOND AMOUNT: 16,225 ANNUAL REPORT YEAR: 92

NONCOMP NOTICES: 0 0 DATE ISSUED: / / DATE RESOLVED: / / VIOLATIONS: 0 0 DATE ISSUED: / / DATE RESOLVED: / / REVISIONS: 0 0 DATE REC'D: / / DATE APPROVED: / /	١		YTD	Total						
REVISIONS: 0 0 DATE REC'D: / / DATE APPROVED: / /		NONCOMP NOTICES:	0	0	DATE ISSUED:	/	/	DATE RESOLVED:	1	1
		VIOLATIONS:	0	0	DATE ISSUED:	1	1	DATE RESOLVED:	1	1
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		REVISIONS:	0	0	DATE REC'D:	1	1	DATE APPROVED:	1	1
AMENDMENTS: 0 0 DATE REC'D: / / DATE APPROVED: / /		AMENDMENTS:	0	0	DATE REC'D:	1	1	DATE APPROVED:	1	1

MRC ORIGINALLY PERMITTED THIS SITE. THE NOI WAS TRANSFERRED TO THE CLAIM HOLDER (BILL WILSON) IN THE FALL OF 1982 WHEN THE MINE WENT ON STANDBY. INTERIM RECLAMATION WORK WAS PERFORMED AT THIS TIME ALSO. THE MINE WAS REOPENED BY A LESSEE IN LATE 1985. IT APPEARS THAT THE MINE MAY AGAIN BE ON STANDBY. 1992 REPORT STATES THAT @2 ACRES ARE DISTURBED. MINE STILL ON STANDBY STATUS.